


Air Preparation Assembly

DESCRIPTION:

Hypertherm high definition plasma cutting systems require 115 PSI clean, dry, oil-free air that meets ISO spec 8573-1 Class 1.4.2. The Air Preparation Assembly ships fully assembled and ready for installation either to a wall or to the optional gas console stand.

FEATURES:

- A. Water separator
- B. Inlet connection (air)
- C. Pressure regulator
- D. Desiccant drier
- E. Coalescing filter
- F. Shut off valve
- G. Outlet connection (air)
- H. Mounting plate (wall or stand)



APPLICATIONS:

- Drying and cleaning compressed air for plasma cutting